


Workstation Benching Dividers – Installation



Locate Panel Divider in place and use provided square template to position panel and lower floor glides to level the panel.

Then lift panel, remove protective tape paper and lower panel into position and make sure tape adheres to worksurface.

Once Panel Divider is firmly in place, position 4x4 angle bracket center on the panel, then drill pilot holes into the panel as not to split panel. Then drive long screws into panel and short screws into the worksurface.

Double check floor area and again make sure glides push snug into the carpet, then test for stability.

